Airco Plating Co. Inc.

Miami, Florida FAA Certificate # 9APR710Y

Subcontrator Evauation Survey				
Part 1 - General Information				
Business Name: Air	co Plating Co. Inc. (A	irco)		
Street Address: 365	0 NW 46th Street M	/liami, Florida 33142	2	
Telephone: (305) 633-2476		Fax: (305) 635-4153		
Quality Conact: Michael King		Title: President / Accountable Manager		
Quality E-mail: mking@aircoplating.com		Company Web Site: AircoPlating.com		
	Type of	Business		
FAA Repair	Station (RS)	Specialized Service Provider		
Plating		Non-Destructive Testing		
Shot Peening		Chrome Grinding		
Repair Station Personnel				
Total - 12	Inspection - 2	Quality - 2	Production - 6	
Facility				
One Building	Block Construction	35,000 square feet	Inception - 1955	
	Associated	Documents		
Other related documents including AirAgency Certificate, Operations Specifications, A449 Anti-Drug and Alcohol Misuse Prevention Program and a Full List of Capablities can be found on our web site at www.aircoplating.com.				

Airco Plating Co. Inc. Miami, Florida FAA Certification # 9APR710Y

Pal	t 2 - Survey			
	A - Certification Information	Yes	No	N/A
1	Is Current Air Agency Certficate displayed?	Х		
2	Is Current Operations Specifications displayed?	Х		
3	Is the Repair Station EASA Certified?		Χ	
4	Does Repair Station have DOT Anti-Drug and Alcohol Misuse Prevention Program in place?	X		
5	Individual Plan managed by OM Management.	Χ		
	B - Operation and Organization	Yes	No	N/A
1	Does the RS have a Capabilities List?		Χ	
2	Does the RS have an organizational chart?	Х		
3	Does it identify relationships and reporting chains?	Х		
4	Are written process procedures used in production?	Х		
5	Is there a procedure to insure they are current?	Х	,	
6	Is there a system insuring tech data is current?	Χ		
7	Does the RS have evidence establishing that FAA Anti- Drug / Alcohol Testing program is current?	X		
8	Is Pre-Employment drug testing documented?	Χ		
	C - Training	Yes	No	N/A
1	Is RS employee training properly documented?	Х	*	
2	Are records for past and current employees maintained at the RS for at least two years	X		
3	Are OTJ and classroom training methods used?	Χ		
4	Are training and certification records properly stored?	Х		

Airco Plating Co. Inc Miami, Florida FAA Certificate # 9APR710Y

	D - Housing and Facility	Yes	No	N/A
1	Are work areas clean and free from clutter?	Х		
2	Is there adequate space necessary to perform required work?	X		
3	Are traffic areas and emergency exits free from obstruction and hazards?	Х		
4	Is there protection from fire and theft?	X		
5	Does housing adequately protect parts, materials and customer units from damage?	X		
6	Are fire extinguishers up to date and accessible to all personnel?	X		
	E - Record of Work Performed	Yes	No	N/A
1	Do routings document who performed work?	X		
2	Do routings document who inspected work?	X		
3	Are all work records kept at least 2 years?	Х		
	F - Quality Control	Yes	No	N/A
1	Are quality personnnel separate from Production?	X		
2	Is the Quality Control Manual (QCM) current?	X		
3	Is the QCM available to RS employees?	X		
4	Is RS technical data maintained and current?	X		
5	Does RS maintain an inspection roster?	X		
6	Does RS maintain a system for stamp control?	Х		
7	Are NDT (MPI/FPI) personnel properly certified?	Х		
8	Does RS have an internal audit program?	Х		
9	Does RS use subcontractors to perform any maintenance functions?		Χ	

Airco Plating Co. Inc. Miami, Florida FAA Certificate # 9APR710Y

	G - Tool Calibration Program	Yes	No	N/A
1	Does the RS maintain a documented calibration program?	Х		
2	Are tool calibration records up to date?	Х		
3	Are tools marked showing calibration dates and vendors performing calibration work?			
4	Are standards used traceable to NIST?	Χ		
5	Are calibrations peformed by outside vendors?	Χ		
6	Is there a system identifying tools that are included in the calibration program?	Х		
7	Is there a person responsible for the program?	Χ		
	H - Material Control	Yes	No	N/A
1	Does the RS have a shelf life program?	Х		
2	Are expiration dates marked on items in the shelf life program?	Х		
3	Are expired materials removed from inventory?	Х		
I - Storage and Shipping		Yes	No	N/A
1	Are parts and materials properly identified & stored?	Х		
2	Is there a quarantine area for holding rejected parts?	Х		
3	Are parts properly identified in the RS?	Х		
4	Are parts stored in a way to protect from damage?	Х		
5	Are parts returned / shipped in proper containers	Х		
J - Scrap Parts		Yes	No	N/A
1	Suspect parts are returned to customer for evaluation?	Х		
2	Are records kept verifying return of damage parts?	Х		

Airco Plating Co. Inc Miami, Florida FAA Certificate # 9APR710Y

Clarification of "No" responses				
Part 2 (A) 3 - Airco is	Part 2 (A) 3 - Airco is currently not EASA certified.			
Part 2 (B) 1 - Airco as	Part 2 (B) 1 - Airco as a specialized service provider does not have a capabilities List			
Part 2 (F) 9 - Airco cu maintenance functions	rrently does not use sub-contacto s.	rs to perform any		
Part 3 - Certification S	statement			
"To the best of my knowledge the information and statements presented in this survey are true and accurate".				
	President, Accountable Manag	er July 1, 2012		
Michael G. King				
Part 4 - Audit Status				
Part 4 to be	filled out by customer personnel only (r	not Airco personnel)		
Accepted	Conditionally Accepted	Unacceptable		
Comments:				
Follow-up Action Required: Yes or No				
Signature:		Date:		
Company:				
Next Survey Due: Computer Update:				